



VEHICLE INSPECTION REPORT

GX21LUF

Ford Fiesta 1.0 EcoBoost 95 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2021	Keys	2	CAP Clean	£7,975.00
Year	2021	Service history	Yes	CAP Average	£7,025.00
Mileage	27,138 Miles Warranted	Service documents	Printout	CAP Below	£6,050.00
Fuel Type	PETROL	Number of stamps	1	Gearbox	MANUAL
Colour	RED	Last service date	09/09/2025	Gears	6
VIN	WF0JXXGAHJLT14461	Last service miles	21,466	Doors	5
Body Style	Hatchback	MOT Due	30/04/2027		

£90 ADDITIONAL FEE

Last service 09/09/2025 at 21,466 miles- 1 service

Tyres




NSF	NEXEN	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	NEXEN	6.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 30mm



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Dented
With Paint Damage



13: Door osf
Dented
With Paint Damage



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK