



VEHICLE INSPECTION REPORT

LS70GZL

Renault Clio 1.0 TCe 100 Iconic 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	14/09/2020	Body Style	Hatchback	Last service miles	25,953
Year	2020	Keys	2	MOT Due	13/09/2026
Mileage	30,137 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Printout	Gears	5
Colour	ORANGE	Number of stamps	3	Doors	5
VIN	VF1RJA00163159576	Last service date	27/08/2025		

£90 ADDITIONAL FEE

LAST SERVICE 27/08/2025 @ 25,953 MILES (3 SERVICES, ALL MAIN DEALER) Service spanner's display
Sos system check warning message display

Tyres


NSF	HIFLY	5.0mm
NSR	BRIDGESTONE	4.0mm
OSF	KUMHO	5.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Poor Previous Repair
Poor Paint




5: Door nsr
Poor Previous Repair
Poor Paint




6: Qtr Panel nsr
Chipped
1 To 5



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Roof
Scratched
Over 25mm Thru Paint



9: Door osr
Chipped
1 To 5



10: Door osf
Chipped
Edge Chip



11: Wing osf
Scratched
UpTo 25mm Thru Paint



12: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK