



VEHICLE INSPECTION REPORT

GU15MGV

Vauxhall Astra 1.4i 16V Excite 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/03/2015	Keys	2	CAP Clean	£1,225.00
Year	2015	Service history	Yes	CAP Average	£820.00
Mileage	91,441 Miles Warranted	Service documents	Printout	CAP Below	£400.00
Fuel Type	PETROL	Number of stamps	7	Gearbox	MANUAL
Colour	RED	Last service date	09/03/2026	Gears	5
VIN	W0LPC6EB0FG052777	Last service miles	88,589	Doors	5
Body Style	Hatchback	MOT Due	29/03/2027		

last service 9/3/26 @ 88,589 miles (7 services)

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	4.0mm
OSR	MAZZINI	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Fascia Trim
Damaged
Replace



3: Fascia Trim
Damaged
Replace



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm




7: Wing nsf
Chipped
Over 5mm



8: Door nsf
Dented
With Paint Damage



9: Sill ns
Dented
With Paint Damage



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Up To 50mm



13: Bumper Rear
Dented
With Paint Damage



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osf
Scratched
Over 50mm



16: Door osf
Dented
With Paint Damage



17: Door osf
Dented
With Paint Damage



18: Wing osf
Dented
Between 10mm + 30mm



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK