



VEHICLE INSPECTION REPORT

FN65RUA

Vauxhall Astra 1.6 CDTi 16V ecoFLEX Design 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	03/09/2015	Body Style	Estate	Last service miles	83,957
Year	2015	Keys	2	MOT Due	02/09/2026
Mileage	85,116 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	GREEN	Number of stamps	10	Doors	5
VIN	W0LPD8E69G8002757	Last service date	04/08/2025		

Last service 04/08/2025 at 83,957 miles- 10 services

Tyres


NSF	NEXEN	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
 Scratched
 UpTo 25mm Thru Paint



10: Bumper Rear
 Scratched
 Over 100mm Thru Paint



11: Tailgate
 Scratched
 UpTo 25mm Thru Paint



12: B Post os
 Dented
 Between 10mm + 30mm



13: Qtr Panel osr
 Dented
 Between 10mm + 30mm



14: Door osr
 Scratched
 Over 25mm Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Chipped
UpTo 10mm



19: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK