



VEHICLE INSPECTION REPORT

RJ16RKE

Kia Rio 1.4 CRDi 3 5dr

Non Runner
Inspection

Vehicle	
Serious Damage?	No
VAT	Margin
V5	Photocopy



Details

Reg. date	23/06/2016	Body Style	Hatchback	Last service miles	76,176
Year	2016	Keys	2	MOT Due	19/07/2027
Mileage	86,301 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	9	Doors	5
VIN	KNADN514LG6678170	Last service date	26/06/2024		

COPY OF V5

Last service 26/06/2024 at 76,176 miles- 9 services (5 main dealer) Non runner
Radio screen faulty

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	GOODYEAR	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear Moulding
Broken
Replace



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Dented
Between 10mm + 30mm



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	Fault		
Windows	OK	Radio	Fault
		Steering	OK