



VEHICLE INSPECTION REPORT

HG63LSC

Honda Civic 1.8 i-VTEC ES 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	31/01/2014	Body Style	Hatchback	Last service miles	45,349
Year	2014	Keys	2	MOT Due	04/11/2026
Mileage	166,915 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Electronic / Online	Gears	6
Colour	BROWN	Number of stamps	1	Doors	5
VIN	SHHFK2760DU005834	Last service date	15/11/2016		

last service 15/11/16 @ 45,349 miles (1 main dealer) confirmed by Horizon Motor Company (Poole)

Tyres


NSF	DAVANTI	5.0mm
NSR	BRIDGESTONE	4.0mm
OSF	DAVANTI	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Moulding
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Poor Previous Repair
Paint Flake



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm




9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Poor Previous Repair
Rippled UpTo 30%



13: Door osf
Dented
With Paint Damage



14: Wheel osf
Scratched
Over 50mm



15: Wing osf
Chipped
1 To 5



16: Sill os
Scratched
Over 25mm Thru Paint



17: Roof
Rusted
Over 5mm



18: A Post ns
Chipped
Edge Chip



19: A Post os
Scratched
Over 25mm Thru Paint



20: Switches And Controls
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK