



VEHICLE INSPECTION REPORT

MJ62VDV

Mercedes-Benz B Class B180 CDI BlueEFFICIENCY SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/01/2013	Body Style	MPV	Last service miles	78,200
Year	2013	Keys	2	MOT Due	26/11/2026
Mileage	80,407 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WDD2462002J137329	Last service date	27/11/2025		

£90 ADDITIONAL FEE

LAST SERVICE 27/11/2025 @ 78,200 MILES (6 SERVICES, 1 MAIN DEALER) Airbag malfunction message displayed

Tyres

NSF	BUDGET	3.0mm
NSR	AUTOGREEN	5.0mm
OSF	AUTOGREEN	4.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Other
N/A
N/A




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint




6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
Between 10mm + 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Dented
With Paint Damage




12: Tailgate
Chipped
1 To 5




13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
Between 10mm + 30mm



17: Door osf
Scratched
Over 25mm Thru Paint



18: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK