



VEHICLE INSPECTION REPORT

DA70RZM

Toyota RAV4 2.5 VVT-i Hybrid Dynamic 5dr CVT 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2020	Body Style	Estate	Last service miles	52,726
Year	2020	Keys	2	MOT Due	07/11/2026
Mileage	81,766 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	1
Colour	SILVER	Number of stamps	2	Doors	5
VIN	JTMW53FV90D502983	Last service date	03/09/2024		

£90 ADDITIONAL FEE

LAST SERVICE 03/09/2024 @ 52,726 MILES (2 SERVICES, BOTH MAIN DEALER)

Tyres

NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	3.0mm
OSF	GOODYEAR	Damaged
OSR	GOODYEAR	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Tyre osf
Damaged
Replace



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Up To 50mm



5: Wing Front Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Bumper Rear
Scratched
Up To 25mm Thru Paint



12: Qtr Panel osr
Chipped
1 To 5



13: Door osr
Dented
Between 10mm + 30mm



14: Door osr
Chipped
1 To 5



15: Door osf
Chipped
1 To 5



16: Flasher Side Repeater os
Broken
Replace



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK