



VEHICLE INSPECTION REPORT

GY66NFM

Renault Clio 0.9 TCE 90 Dynamique Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/12/2016	Keys	2	CAP Clean	£2,150.00
Year	2016	Service history	Yes	CAP Average	£1,725.00
Mileage	107,428 Miles Warranted	Service documents	Service Book	CAP Below	£1,350.00
Fuel Type	PETROL	Number of stamps	7	Gearbox	MANUAL
Colour	BLACK	Last service date	26/06/2026	Gears	5
VIN	VF15RE20A55437223	Last service miles	105,967	Doors	5
Body Style	Hatchback	MOT Due	16/01/2027		

£90 ADDITION FEE

Last service 26/06/2026 at 105,967 miles- 7 services

Book and print

Tyres


NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	RAPID	6.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
Edge Chip



5: Qtr Panel osr
Chipped
1 To 5



6: Wheel osr
Corroded
Light



7: Qtr Panel osr
Dented
Between 10mm + 30mm



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
1 To 5



12: Door nsf
Chipped
Edge Chip



13: Door nsf
Chipped
1 To 5



14: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Wing nsf
Scratched
Over 25mm Thru Paint



16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Scratched
25 to 100mm Thru Paint



18: Bonnet
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm



20: Door osr
Dented
2 Or Less UpTo 10mm



21: Door nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK