



VEHICLE INSPECTION REPORT

GU15AHK

Skoda Fabia 1.2 TSI 90 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	14/03/2015	Keys	2	CAP Clean	£4,050.00
Year	2015	Service history	Yes	CAP Average	£3,500.00
Mileage	68,935 Miles Warranted	Service documents	Printout	CAP Below	£2,925.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	BLUE	Last service date	07/04/2025	Gears	5
VIN	TMBFM6NJ6FZ028554	Last service miles	67,035	Doors	5
Body Style	Hatchback	MOT Due	05/04/2026		

Last Service: 07/04/2025 at 67035 miles. (9 services (2 main dealer))

Tyres

NSF	NEXEN	4.0mm
NSR	NEXEN	4.0mm
OSF	BUDGET	5.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips


No Image



4: Wheel nsf
Scratched
Up To 50mm



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
Over 30mm




8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Chipped
Multiple Chips



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Chipped
1 To 5




13: Wheel osr
Scratched
Up To 50mm



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Door osr
Scratched
Over 25mm Not Thru Paint



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK