



VEHICLE INSPECTION REPORT

PN64ZZT

Nissan Qashqai 1.5 dCi Acenta Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/10/2014	Body Builder	__other	MOT Due	15/09/2025
Year	2014	Keys	2	CAP Clean	£4,025.00
Mileage	80,978 Miles Warranted	Service history	Yes	CAP Average	£3,400.00
Fuel Type	Diesel	Service documents	Service Book	CAP Below	£2,775.00
Colour	BLUE	Number of stamps	6	Gearbox	MANUAL
VIN	SJNFAAJ11U1216063	Last service date	06/09/2023	Gears	6
Body Style	Hatchback	Last service miles	67,806	Doors	5

Last Service - 6.09.2023 at 67806 miles (6 services)

Tyres

NSF	BRIDGESTONE	Worn
NSR	BUDGET	5.0mm
OSF	BRIDGESTONE	Worn
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos




1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Chipped
1 To 5




4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




5: Wheel osr
Scratched
Over 50mm



6: Door osr
Chipped
1 To 5



7: Door osr
Scratched
Over 25mm Not Thru Paint




8: Door osf
Chipped
Multiple Chips



9: Wing osf
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm



11: Bonnet
Chipped
1 To 5



12: Bonnet
Scratched
Over 25mm Not Thru Paint



13: Bumper Front
Chipped
Multiple Chips



14: Wheel nsf
Scratched
Over 50mm

No Image



15: Wing nsf
Scratched
Over 25mm Not Thru Paint

16: Door nsf
Chipped
1 To 5

No Image



17: Door nsf
Scratched
Over 25mm Not Thru Paint

18: Door nsr
Chipped
1 To 5

No Image



19: Door nsr
Scratched
Over 25mm Not Thru Paint

20: Wheel nsr
Scratched
Over 50mm

No Image

21: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



22: Glass Roof
Scratched
Over 30mm

No Image

23: Tyre nsf
Worn
Replace



25: Roof
Dented
Hail - Moderate

No Image

24: Tyre osf
Worn
Replace

No Image

26: Tyre nsf
Worn
Replace

No Image

27: Tyre osf
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		