



VEHICLE INSPECTION REPORT

GU10RVE

Toyota Verso 1.6 V-matic TR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/03/2010	Body Style	MPV	MOT Due	24/01/2027
Year	2010	Keys	3	Gearbox	MANUAL
Mileage	85,019 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	PETROL	Service documents	Electronic & Paper	Doors	5
Colour	SILVER	Number of stamps	6		
VIN	NMTDE26R80R004782	Last service date	08/11/2017		

last service 8/11/17 mileage incorrect (6 main dealer) confirmed by Yeomans Toyota (Eastbourne) / print mileage recorded incorrectly on printout services in 2017, 2016, 2013 & 2012 invoice mileage recorded incorrectly on MOT history in 2019 Noisy engine

Tyres

NSF	GRENLANDER	5.0mm
NSR	GRENLANDER	5.0mm
OSF	GRENLANDER	5.0mm
OSR	GRENLANDER	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



2: Bonnet
Chipped
1 To 5

1: Seat Base Cover of
Torn
Over 3mm



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Wing nsf
Poor Previous Repair
Rippled UpTo 30%



8: Door nsf
Poor Previous Repair
Poor Paint



10: Wheel nsr
Scratched
Over 50mm

9: Door nsr
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Scratched
UpTo 25mm Thru Paint



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



18: Door osf
Scratched
Over 25mm Thru Paint

17: Door osr
Dented
With Paint Damage



19: Sill Panel Trim os
Scratched (Painted)
Over 25mm Thru Paint



20: Wing osf
Dented
Between 10mm + 30mm



21: Wheel osf
Scratched
Up To 50mm



22: Screen Front
Scratched
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK