



VEHICLE INSPECTION REPORT

LS56PXN

BMW X3 2.0d SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	08/12/2006	Body Style	Estate	Last service miles	166,046
Year	2006	Keys	2	MOT Due	13/09/2026
Mileage	181,744 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	9	Doors	5
VIN	WBAPD12080WG47233	Last service date	30/08/2022		

LAST SERVICE 30/08/2022 @ 166,046 MILES (9 SERVICES)

Tyres

NSF	MICHELIN	5.0mm
NSR	VREDESTEIN	4.0mm
OSF	JOYROAD	6.0mm
OSR	VREDESTEIN	4.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm




2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Bonnet
Dented
With Paint Damage



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Tailgate
Chipped
1 To 5



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint




17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Roof
Dented
Over 30mm



20: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK