



VEHICLE INSPECTION REPORT

LB66OYM

Peugeot 2008 1.2 PureTech 110 GT Line 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	10/02/2017	Keys	2	CAP Clean	£6,900.00
Year	2017	Service history	Yes	CAP Average	£6,000.00
Mileage	34,912 Miles Warranted	Service documents	Service Book	CAP Below	£5,075.00
Fuel Type	Petrol	Number of stamps	8	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	06/02/2025	Gears	6
VIN	VF3CUHNZTHY009643	Last service miles	33,353	Doors	5
Body Style	Hatchback	MOT Due	09/02/2026		

Last Service - 06.02.2025 at 33353 miles (8 main dealer services)

Tyres		
NSF	MICHELIN	3.0mm
NSR	GOODYEAR	3.0mm
OSF	MICHELIN	5.0mm
OSR	GOODYEAR	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Park assist camera
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Wheel nsr
Scratched
Over 50mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Chipped
Multiple Chips

No Image

No Image

11: Bumper Rear
Scratched
Over 25mm Not Thru Paint


12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Wheel osr
Scratched
Over 50mm

No Image


14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Door osr
Dented
Over 30mm



16: Door osf
Dented
2 Or Less UpTo 10mm



17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		