



VEHICLE INSPECTION REPORT

AE70AVM

Mitsubishi Shogun Sport 2.4 DI-DC 4 5dr Auto 4WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	15/01/2021	Body Style	Estate	MOT Due	14/01/2027
Year	2021	Service history	Yes	Gearbox	AUTOMATIC
Mileage	37,170 Miles Warranted	Service documents	Printout	Gears	8
Fuel Type	DIESEL	Number of stamps	2	Doors	5
Colour	SILVER	Last service date	07/07/2023		
VIN	MMAGUKS10JH001297	Last service miles	22,871		

£90 ADDITIONAL FEE

Last service 07/07/2023 at 22,871 miles- 2 services Astc system service required

Abs warning light is on

Traction control light is on

Tyres

NSF	MAZZINI	8.0mm
NSR	BRIDGESTONE	4.0mm
OSF	MAZZINI	8.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Full size spare wheel
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Wheel nsf
Scratched
Up To 50mm



7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Door nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Dented
Over 30mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Scratched
UpTo 25mm Thru Paint



14: Tailgate Trim Panel
Scratched (Painted)
Over 25mm Thru Paint



15: Roof
Dented
Between 10mm + 30mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Scratched
UpTo 25mm Thru Paint



19: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK