



VEHICLE INSPECTION REPORT

ET12AXX

Nissan Qashqai+2 2.0 Tekna 5dr 4WD CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/07/2012	Keys	2	CAP Clean	£4,175.00
Year	2012	Service history	Yes	CAP Average	£3,550.00
Mileage	70,423 Miles Warranted	Service documents	Service Book	CAP Below	£2,925.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	CVT
Colour	RED	Last service date	06/05/2021	Gears	1
VIN	SJNJBNI10U7137276	Last service miles	70,002	Doors	5
Body Style	Hatchback	MOT Due	10/05/2026		

Last Service - 06.05.2021 at 70002 miles (12 services)

Tyres


NSF	MICHELIN	4.0mm
NSR	HIFLY	4.0mm
OSF	MICHELIN	4.0mm
OSR	HIFLY	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
Multiple Chips



6: Door nsr
Dented
With Paint Damage




7: Qtr Panel nsr
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Wing osf
Chipped
1 To 5




10: Wing osf
Scratched
Over 25mm Not Thru Paint



11: Wheel osf
Scratched
Over 50mm



12: Door osf
Dented
Over 2 UpTo 10mm



13: Door osf
Scratched
Over 25mm Not Thru Paint



14: Door osr
Chipped
1 To 5

No Image

15: Door osr
Scratched
Over 25mm Not Thru Paint

No Image

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Bumper Rear
Chipped
Multiple Chips

No Image

19: Bumper Rear
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		