



VEHICLE INSPECTION REPORT

RK63OCE

Dacia Sandero Stepway 0.9 TCe Laureate 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 06/09/2013

Year 2013

Mileage 73,362 Miles
Warranted

Fuel Type PETROL

Colour BLUE

VIN UU15SDAAC48848981

Body Style Hatchback

Keys 1

Service history Yes

Service documents Service Book

Number of stamps 4

Last service date 29/10/2017

Last service miles 38,258

MOT Due 01/01/2027

Gearbox MANUAL

Gears 5

Doors 5

LAST SERVICE 29/10/2017 @ 38,258 MILES (4 SERVICES, 2 MAIN DEALER)

Tyres

NSF GOODRIDE Illegal

NSR PIRELLI 5.0mm

OSF GOODRIDE 1.0mm

OSR GOODYEAR 5.0mm

Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Steel wheels
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Central locking
- Telephone
- Air conditioning
- ABS
- Remote central locking

Photos






Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Fog Lamp Surround is
Scratched (Painted)
Over 25mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wing Front Arch Extension nsf
Scuffed (Unpainted)
Over 100mm




6: Wing nsf
Chipped
1 To 5



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door nsf
Dented
Over 30mm



9: Door nsr
Dented
With Paint Damage



10: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



12: Parking Sensor Rear
Missing
Replace



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Tailgate
Scratched
UpTo 25mm Thru Paint



15: Door osr
Dented
With Paint Damage




16: Door osf
Dented
With Paint Damage



17: Wing osf
Chipped
1 To 5



18: Roof
Dented
Between 10mm + 30mm



19: Aperture Seal nsf
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK