



VEHICLE INSPECTION REPORT

AY67VGJ

Peugeot 2008 1.2 PureTech Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	26/01/2018	Body Style	Hatchback	Last service miles	34,006
Year	2018	Keys	2	MOT Due	24/08/2026
Mileage	37,467 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	8	Doors	5
VIN	VF3CUHMZ6HY175250	Last service date	12/08/2025		

last service 12/8/25 @ 34,006 miles (8 services 6 main dealer)
MOT expires 24/8/26 Abs and traction control lights are on
Service spanner display
Paint faded
Tyre monitoring system fault

Tyres

NSF	JOYROAD	5.0mm
NSR		2.0mm
OSF	JOYROAD	5.0mm
OSR	SUPERIA	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Service indicator
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos




1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: A Post ns
Poor Previous Repair
Paint Flake



5: Roof
Poor Previous Repair
Paint Flake



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Tailgate
Chipped
1 To 5



11: Qtr Panel osr
Chipped
1 To 5



12: Wheel osr
Corroded
Light



13: Door osr
Scratched
UpTo 25mm Thru Paint



14: Door osf
Chipped
Edge Chip



15: Wing osf
Chipped
1 To 5

16: Wheel osf
Scratched
Over 50mm



17: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK