



VEHICLE INSPECTION REPORT

GX71VPV

Jaguar F-Pace 2.0 P400e R-Dynamic S 5dr Auto AWD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	12/11/2021	Keys	2	CAP Clean	£17,650.00
Year	2021	Service history	Yes	CAP Average	£16,300.00
Mileage	79,883 Miles Warranted	Service documents	Printout	CAP Below	£14,950.00
Fuel Type	HYBRID ELECTRIC	Number of stamps	3	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	29/07/2025	Gears	8
VIN	SADCA2AY5MA687846	Last service miles	61,618	Doors	5
Body Style	Estate	MOT Due	29/09/2026		

£90 ADDITIONAL FEE

LAST SERVICE 29/07/2025 @ 61,618 MILES (3 SERVICES, 2 MAIN DEALER)

Tyres


NSF	PIRELLI	2.5mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	3.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Door osf
Dented
2 Or Less UpTo 10mm



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Bumper Rear
Chipped
Multiple Chips



8: Tailgate
Poor Previous Repair
Poor Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Door nsf
Chipped
Edge Chip



11: Wheel nsf
Scratched
Over 50mm



12: Wing nsf
Chipped
1 To 5



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Chipped
1 To 5



15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK