



VEHICLE INSPECTION REPORT

OY12FBJ

Vauxhall Astra 1.6i 16V Excite 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/03/2012	Body Style	Hatchback	Last service miles	81,245
Year	2012	Keys	2	MOT Due	05/06/2027
Mileage	102,186 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	9	Doors	5
VIN	W0LPD6EDXBG152071	Last service date	29/08/2023		

LAST SERVICE 29/08/2023 @ 81,245 MILES (9 SERVICES, 3 MAIN DEALER) Noisy pulleys

Tyres		
NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Roof
Rusted
Over 5mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Handle Outer nsr
Scratched (Painted)
UpTo 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



13: Bumper Rear
Scratched
Over 100mm Thru Paint




14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Between 10mm + 30mm



17: Door osr
Chipped
1 To 5




18: Door osf
Scratched
Rusted



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Poor Previous Repair
Paint Flake



21: Screen Front
Cracked
Replace

22: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK