



VEHICLE INSPECTION REPORT

PO14WDS

Nissan Juke 1.6 Tekna 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/03/2014	Body Style	Hatchback	Last service miles	70,073
Year	2014	Keys	2	MOT Due	14/01/2027
Mileage	73,344 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	PETROL	Service documents	Service Book	Gears	1
Colour	RED	Number of stamps	10	Doors	5
VIN	SJNFBAF15U6514542	Last service date	16/06/2026		

Last Service - 16.06.2026 at 70073 miles (10 services)

Gearbox rattle

Sd card missing for sat nav

Tyres


NSF	BUDGET	Damaged
NSR	DEBICA	2.0mm
OSF	MICHELIN	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Poor Paint




5: Door nsf
Poor Previous Repair
Rippled UpTo 30%



6: Door nsr
Chipped
Multiple Chips



7: Wheel nsr
Scratched
Over 50mm



8: B Post ns
Dented
Between 10mm + 30mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
Multiple Chips



13: Tyre nsf
Damaged
Replace



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Over 50mm



18: Roof
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	Fault	Steering	OK