



VEHICLE INSPECTION REPORT

GU57XSN

Citroen Xsara Picasso 2.0i 16V Exclusive 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/09/2007	VIN	VF7CHRFNF25929342	Gearbox	AUTOMATIC
Year	2007	Body Style	Estate	Gears	4
Mileage	142,262 Miles Warranted	Keys	1	Doors	5
Fuel Type	PETROL	Service history	None		
Colour	SILVER	MOT Due	23/10/2026		

NO SERVICE Engine tapping when idle
Service spanner displayed
Osf front window faulty

Tyres

NSF	MAZZINI	Damaged
NSR	MAZZINI	5.0mm
OSF	MAZZINI	3.0mm
OSR	MAZZINI	5.0mm
Spare		

Features


- Cruise control
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Number Plate Front
Broken
Replace



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Poor Previous Repair
Poor Paint



7: Door nsf
Poor Previous Repair
Poor Paint



8: Door nsr
Poor Previous Repair
Rippled UpTo 30%



9: Qtr Panel nsr
Dented
With Paint Damage




10: Wheel nsr
Scratched
Over 50mm



11: Lamp nsr
Broken
Replace




12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Wiper Rear
Broken
Replace



14: Tailgate
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Dented
With Paint Damage



16: Wheel osr
Scratched
Over 50mm




17: Sill os
Rusted
Over 5mm



18: Door osr
Dented
Between 10mm + 30mm



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Aperture Seal osf
Broken
Replace



23: Screen Front
Cracked
Replace



24: Tyre nsf
Damaged
Replace



25: Switches And Controls
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK