



VEHICLE INSPECTION REPORT

YA57BXD

BMW 3 Series 330i M Sport 2dr Auto

Cat: S Incident History

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date	22/12/2007	Body Style	Coupe	Last service miles	31,338
Year	2007	Keys	2	MOT Due	14/09/2026
Mileage	44,695 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	8	Doors	2
VIN	WBAWE72080PG15050	Last service date	16/09/2020		

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair
last service 16/9/20 @ 31,338 miles (8 services) Radio screen faulty

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BUDGET	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Service indicator
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Chipped
1 To 5



5: Wheel nsr
Scratched
Over 50mm



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Dented
Between 10mm + 30mm



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Qtr Panel osr
Poor Previous Repair
Poor Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osf
Poor Previous Repair
Poor Paint



12: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK