



VEHICLE INSPECTION REPORT

ST17NFM

Nissan Qashqai 1.2 DiG-T Tekna [Non-Panoramic] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/05/2017	Body Style	Hatchback	Last service miles	83,861
Year	2017	Keys	2	MOT Due	04/04/2027
Mileage	90,339 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	9	Doors	5
VIN	SJNFEAJ11UZ036030	Last service date	31/03/2026		

Last Service - 31.03.2026 at 83861 miles (9 main dealer services)

Tyres



NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm




4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Chipped
Edge Chip



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Dented
2 Or Less Up To 10mm



11: Tailgate
Chipped
1 To 5



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Dented
Between 10mm + 30mm



16: Door osf
Chipped
Edge Chip



17: Wing osf
Scratched
UpTo 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		