



VEHICLE INSPECTION REPORT

ST20SBU

Vauxhall Corsa 1.2 Turbo Elite Nav Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/08/2020	Body Style	Hatchback	Last service miles	64,735
Year	2020	Keys	2	MOT Due	25/08/2026
Mileage	84,705 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	VXKUPHNKKL4322370	Last service date	19/08/2025		

Last service 19/08/2025 at 64,735 miles- 5 main dealer services Reverse camera faulty

Tyres

NSF	WANLI	5.0mm
NSR	BUDGET	5.0mm
OSF	SUNNY	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wing nsf
Poor Previous Repair
Rippled UpTo 30%



4: Wheel nsf
Scratched
Over 50mm



5: A Post ns
Chipped
1 To 5



6: Door nsf
Dented
Over 30mm



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Dented
Over 30mm



12: C Post os
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK