



VEHICLE INSPECTION REPORT

AO69VYA

Toyota RAV4 2.5 VVT-i Hybrid Design 5dr CVT 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/02/2020	Body Style	Estate	Last service miles	90,062
Year	2020	Keys	2	MOT Due	21/02/2027
Mileage	90,636 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	6	Doors	5
VIN	JTMW23FV60D037541	Last service date	10/07/2026		

Last service 10/07/2026 at 90,062 miles- 6 main dealer services

Tyres



NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5




4: Door nsf
Chipped
Multiple Chips



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Tailgate
Scratched
Over 25mm Thru Paint




9: Door osr
Scratched
Over 25mm Thru Paint




10: Door osf
Chipped
Edge Chip



11: Wing osf
Chipped
1 To 5



12: Door osf
Dented
Between 10mm + 30mm



13: Roof
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK