



VEHICLE INSPECTION REPORT

DE05BUO

Honda Jazz 1.4 i-DSi SE 5dr CVT-7

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2005	Body Style	Hatchback	Last service miles	59,764
Year	2005	Keys	2	MOT Due	23/11/2026
Mileage	80,731 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	PETROL	Service documents	Service Book	Gears	1
Colour	SILVER	Number of stamps	12	Doors	5
VIN	JHMGD18505S233894	Last service date	03/02/2021		

Last Service - 03.02.2021 at 59764 miles (12 main dealer services) Exhaust blowing

Tyres


NSF	AVON	4.0mm
NSR	TIGAR	5.0mm
OSF	AVON	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Radio/CD
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: A Post ns
Poor Previous Repair
Poor Paint




7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Dented
With Paint Damage



11: B Post ns
Poor Previous Repair
Poor Paint



12: Tailgate
Poor Previous Repair
Poor Paint



13: Qtr Panel osr
Poor Previous Repair
Poor Paint



14: Wheel osr
Scratched
Over 50mm




15: B Post os
Poor Previous Repair
Paint Flake



16: Door osr
Poor Previous Repair
Poor Paint



17: Door osf
Dented
Over 30mm



18: Door osf
Scratched
Over 25mm Thru Paint



19: A Post os
Poor Previous Repair
Paint Flake



20: Wing osf
Poor Previous Repair
Paint Flake



21: Wheel of
Corroded
Light

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK