



VEHICLE INSPECTION REPORT

KN14GKP

Peugeot 3008 1.6 HDi Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2014	Body Style	Hatchback	Last service miles	104,067
Year	2014	Keys	2	MOT Due	14/06/2027
Mileage	110,145 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	4	Doors	5
VIN	VF30U9HD8ES049039	Last service date	02/06/2025		

Last Service - 02.06.2025 at 104067 miles (4 services)
Clutch Replaced 16.10.2024 @ 100627 Miles Engine cover rattling
Reverse camera image blurry

Tyres




NSF	ROYALBLACK	5.0mm
NSR	BUDGET	5.0mm
OSF	ROYALBLACK	5.0mm
OSR	AUTOGREEN	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Scratched
Over 25mm Thru Paint



4: Wheel osr
Corroded
Light



5: Qtr Panel osr
Chipped
1 To 5



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm



9: Door nsr
Chipped
1 To 5



10: Door nsf
Chipped
1 To 5



11: Door nsf
Chipped
Edge Chip



12: Wheel nsf
Scratched
Over 50mm



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5

16: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK