



VEHICLE INSPECTION REPORT

DS20WFN

Ford S-Max 2.0 EcoBlue 190 ST-Line 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply



Details

Reg. date	31/07/2020	Body Style	MPV	Last service miles	62,269
Year	2020	Keys	2	MOT Due	25/01/2027
Mileage	75,742 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	3	Doors	5
VIN	WF0JXXWPCJLA36522	Last service date	25/02/2025		

£100 ADDITIONAL FEE

NO V5

LAST SERVICE 25/02/2025 @ 62,269 MILES (3 SERVICES) Pre collision assist not available message displayed

Tyres

NSF	PIRELLI	6.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	6.0mm
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Chipped
1 To 5



4: A Post ns
Chipped
1 To 5



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Dented
Between 10mm + 30mm



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Wheel osr
Corroded
Light



13: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint




14: Wheel osf
Scratched
Over 50mm



15: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



16: A Post os
Chipped
1 To 5



17: Roof
Chipped
Edge Chip



18: Bumper Front
Poor Previous Repair
Poor Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK