



VEHICLE INSPECTION REPORT

GP21AUV

Kia Rio 1.0 T GDi 48V 118 3 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/06/2021	Body Style	Hatchback	Last service miles	60,473
Year	2021	Keys	2	MOT Due	20/05/2027
Mileage	79,358 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	Service documents	Service Book	Gears	7
Colour	WHITE	Number of stamps	5	Doors	5
VIN	KNADC517VM6545587	Last service date	29/05/2025		

£100 ADDITIONAL FEE

Last service 29/05/2025 at 60,473 miles- 5 services (4 main dealer) Noisy pulleys

Tyres


NSF	NEXEN	3.0mm
NSR	MICHELIN	4.0mm
OSF	NEXEN	3.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Chipped
Edge Chip



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Bumper Reflector osr
Broken
Replace



10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
Chipped
Edge Chip



16: B Post os
Dented
Over 2 UpTo 10mm



17: A Post os
Chipped
1 To 5



18: Roof
Chipped
Edge Chip



19: Wing osf
Chipped
1 To 5



20: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK