



VEHICLE INSPECTION REPORT

RE69PVD

Nissan Qashqai 1.3 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2019	Body Style	Hatchback	MOT Due	31/10/2026
Year	2019	Service history	Yes	Gearbox	MANUAL
Mileage	81,591 Miles Warranted	Service documents	Service Book	Gears	6
Fuel Type	PETROL	Number of stamps	6	Doors	5
Colour	BLUE	Last service date	31/10/2025		
VIN	SJNFFAJ11U2555144	Last service miles	73,144		

Last service 31/10/2025 at 73,144 miles- 6 main dealer services Clutch slipping

Tyres


NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Dented
Over 30mm



6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Scratched
Over 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




10: Tailgate
Dented
Between 10mm + 30mm




11: Bumper Rear
Scratched
25 to 100mm Thru Paint




12: C Post os
Dented
Between 10mm + 30mm



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Scratched
Over 25mm Thru Paint




16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Dented
Between 10mm + 30mm



18: Door osf
Chipped
Edge Chip



19: Wing osf
Scratched
UpTo 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Door Mirror Assy osf
 Scratched (Painted)
 UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
 Average

Upholstery Condition
Odour

Average
 No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		