

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Skoda Citigo 1.0 MPI SE 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	Present		
Details					
Reg. date	22/02/2017	Keys	2	CAP Clean	£2,800.00
Year	2017	Service history	Yes	CAP Average	£2,325.00
Mileage	85,673 Miles Warranted	Service documents	Service Book	CAP Below	£1,850.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	SILVER	Last service date	09/10/2019	Gears	5
VIN	TMBZZZAAZHD617552	Last service miles	30,314	Doors	5
Body Style	Hatchback	MOT Due	21/02/2026		

Last Service - 09.10.2019 at 30314 miles (3 main dealer services)

Tyres			
NSF	FULLRUN	4.0mm	
NSR	FULLRUN	3.0mm	
OSF	FULLRUN	4.0mm	
OSR	LAUFENN	4.0mm	
Spare			

Features

- PAS
- Air conditioning
- Rear headrests
- Isofix child seat anchor points
- · Cloth seat trim
- Rear wiper Climate control Metallic Paint
- •
- Passenger airbag
- Alloy wheels
- Digital radio •
- Front electric windows •
- 3x3 point rear seat belts •
- Central locking
- Body coloured bumpers
- Front head restraints
- Drivers airbag
- Remote central locking

Photos



Eastbourne Car Auctions










Condition Check



Damage Photos







2: Bumper Front Chipped Multiple Chips

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint




4: Wheel nsf Scratched Over 50mm



5: Wing nsf Dented Over 2 UpTo 10mm



6: Door nsf Dented Over 2 UpTo 10mm



7: Door nsf Chipped Edge Chip

No Image

8: Door nsr Scratched Over 25mm Not Thru Paint





9: Wheel nsr Scratched Up To 50mm

CTGO CTGO

10: Qtr Panel nsr Dented 2 Or Less UpTo 10mm

No Image

11: Bumper Rear Chipped Multiple Chips



13: Qtr Panel osr Dented 2 Or Less UpTo 10mm 12: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

14: Door osr Scratched Over 25mm Not Thru Paint

No Image



15: Door osf Scratched Over 25mm Not Thru Paint

16: Wheel osf Scratched Up To 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition A Odour N

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK		Gearbox 1st and Reverse Test	
Brakes OK		Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK