



VEHICLE INSPECTION REPORT

RJ08WGV

Honda Accord Ex+ I-Vtec

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/05/2008	VIN	JHMCM28908C200166	Number of stamps	3
Year	2008	Body Style	Estate	Last service date	30/07/2025
Mileage	94,227 Miles Warranted	Keys	1	Last service miles	91,701
Fuel Type	PETROL	Service history	Yes	MOT Due	27/07/2027
Colour	SILVER	Service documents	Printout		

Last Service - 30.07.2025 at 91701 miles (3 main dealer services)

Tyres

NSF	PIRELLI	4.0mm
NSR	BRIDGESTONE	5.0mm
OSF	FALKEN	3.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Insecure
Action Required



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
2 Or Less UpTo 10mm



8: Door nsf
Chipped
1 To 5



9: A Post ns
Chipped
1 To 5



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Up To 50mm



13: B Post ns
Rusted
Over 5mm



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Tailgate
Rusted
Over 5mm



16: Tailgate
Poor Previous Repair
Rippled UpTo 30%




17: Qtr Panel osr
Rusted
Over 5mm




18: Wheel osr
Scratched
Over 50mm



19: Door osr
Dented
Over 2 UpTo 10mm



20: Door osr
Scratched
UpTo 25mm Thru Paint



21: Door osf
Scratched
Over 25mm Thru Paint




22: Wing osf
Chipped
1 To 5



23: Wheel osf
Scratched
Over 50mm



24: A Post os
Rusted
Over 5mm



25: Roof
Rusted
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No