



VEHICLE INSPECTION REPORT

MJ65NDF

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 4MOTION 5dr 150 DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/09/2015	Body Style	Estate	Last service miles	38,943
Year	2015	Keys	2	MOT Due	21/10/2026
Mileage	159,914 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	DIESEL	Service documents	Service Book	Gears	7
Colour	GREY	Number of stamps	2	Doors	5
VIN	WVGZZZ5NZGW032388	Last service date	17/10/2018		

Last service 17/10/2018 at 38,943 miles- 2 main dealer services
Timing belt replaced 14/01/2026 mileage not recorded Engine tapping while idle
Seats soiled

Tyres


NSF	BUDGET	Damaged
NSR	BUDGET	5.0mm
OSF	BUDGET	3.0mm
OSR	RAPID	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Radio/CD
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm



2: Bumper Front
Chipped
1 To 5



3: Bonnet
Dented
Between 10mm + 30mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




7: Door nsf
Dented
Over 2 UpTo 10mm



8: B Post ns
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Chipped
1 To 5



15: Wheel osr
Scratched
Up To 50mm



16: Qtr Panel osr
Dented
Between 10mm + 30mm



17: Door osr
Dented
Between 10mm + 30mm



18: Door osr
Scratched
UpTo 25mm Thru Paint



19: Door osf
Chipped
Edge Chip



20: Door osf
Chipped
Edge Chip




21: Wing osf
Dented
Between 10mm + 30mm



22: Wing osf
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Up To 50mm



24: Screen Front
Cracked
Replace



25: A Post os
Dented
2 Or Less UpTo 10mm



26: Roof
Chipped
Edge Chip



27: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



28: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



29: Tyre nsf
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK