



VEHICLE INSPECTION REPORT

ST67LMK

Hyundai Tucson 1.6 GDi Blue Drive SE Nav 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2017	Body Style	Estate	MOT Due	17/04/2027
Year	2017	Keys	2	Gearbox	MANUAL
Mileage	75,048 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	PETROL	Number of stamps	1	Doors	5
Colour	GREY	Last service date	23/03/2021		
VIN	TMAJ3811LJJ552191	Last service miles	32,983		

Last Service - 23.03.2021 at 32983 miles (1 services)
Clutch faulty

Tyres



NSF	RAPID	5.0mm
NSR	HANKOOK	3.0mm
OSF	RAPID	3.0mm
OSR	HANKOOK	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Tailgate
Scratched
Over 25mm Thru Paint



9: Roof
Dented
Over 30mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Scratched
UpTo 25mm Thru Paint



15: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK