



VEHICLE INSPECTION REPORT

GU11JFG

Toyota Aygo 1.0 VVT-i Go 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/03/2011	Body Style	Hatchback	Last service miles	68,141
Year	2011	Keys	2	MOT Due	11/03/2027
Mileage	80,330 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	10	Doors	5
VIN	JTDKG18C90N521231	Last service date	07/03/2025		

last service 7/3/25 @ 68,141 miles (10 services 7 main dealer)
mileage recorded incorrectly on MOT history in 2015 High biting point on clutch

Tyres

NSF	ROTALLA	5.0mm
NSR	AVON	5.0mm
OSF	KLEBER	5.0mm
OSR	RAPID	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Sill ns
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Bumper Rear
Insecure
Action Required



12: Other
N/A
N/A



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
With Paint Damage



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Rusted
Over 5mm



19: Screen Front
Cracked
Replace



20: Roof
Rusted
UpTo 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK