



VEHICLE INSPECTION REPORT

PK64KXJ

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	08/11/2014	Body Style	MPV	Last service miles	30,316
Year	2014	Keys	2	MOT Due	13/04/2027
Mileage	31,427 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	11	Doors	5
VIN	W0LSH9EC7F4004751	Last service date	26/03/2026		

Last Service - 26.03.2026 at 30316 miles (11 services)

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Poor Previous Repair
Paint Flake




3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
2 Or Less UpTo 10mm



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Poor Previous Repair
Paint Flake




10: Bumper Rear
Poor Previous Repair
Paint Flake



11: Qtr Panel osr
Chipped
Multiple Chips



12: Wheel osr
Scratched
Over 50mm




13: Sill os
Scratched
UpTo 25mm Thru Paint



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip




16: Door osf
Dented
Between 10mm + 30mm



17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm



19: Wing osf
Poor Previous Repair
Poor Paint



20: Bumper Front Grill
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK