



VEHICLE INSPECTION REPORT

YD59UTZ

BMW X1 xDrive 23d SE 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	23/09/2009	Body Style	Estate	Last service miles	118,084
Year	2009	Keys	2	MOT Due	25/09/2026
Mileage	124,593 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	6	Doors	5
VIN	WBAVP52080VK51537	Last service date	25/09/2024		

last service 25/9/24 @ 118,084 miles (6 services 3 main dealer)

Tyres		
NSF	PIRELLI	6.0mm
NSR	CONTINENTAL	2.0mm
OSF	PIRELLI	6.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Missing
Replace



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint




6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm



9: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Between 10mm + 30mm




11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Tailgate
Scratched
UpTo 25mm Thru Paint




14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint




17: Door osf
Chipped
Edge Chip




18: Wing osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Corroded
Light



20: Screen Front
Chipped
UpTo 10mm



21: Roof
 Scratched
 Over 25mm Thru Paint



22: Wing of
 Dented
 Between 10mm + 30mm



23: Other
 N/A
 N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK