



VEHICLE INSPECTION REPORT

EA59VHV

Ford Fiesta 1.4 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/10/2009	Body Style	Hatchback	Last service miles	58,464
Year	2009	Keys	3	MOT Due	21/10/2026
Mileage	85,628 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	8	Doors	5
VIN	WF0JXXWPJJ9R80836	Last service date	22/10/2020		

last service 22/10/20 @ 58,464 miles (8 services 6 main dealer)
mileage recorded incorrectly on MOT history in 2022,2021 & 2020

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bumper Front Grill
Broken
Replace



5: Wheel nsf
Scratched
Up To 50mm



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wing nsf
Scratched
Up To 25mm Thru Paint



8: Door Mirror Assy nsf
Broken
Replace



9: Door nsf
Dented
With Paint Damage




10: Door nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Roof
Dented
Over 30mm



15: Qtr Panel osr
Dented
Between 10mm + 30mm




16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Over 30mm



19: Door osf
Chipped
1 To 5



20: Door Mirror Assy osf
Broken
Replace



21: Wheel osf
Scratched
Over 50mm



22: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK