



VEHICLE INSPECTION REPORT

MX02RVP

Toyota Celica 1.8 VVTi 3dr

Cat: C
Inspection

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2002	Body Style	Coupe	Last service miles	83,945
Year	2002	Keys	2	MOT Due	22/01/2027
Mileage	88,402 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	18	Doors	3
VIN	JTDDR38T900122542	Last service date	09/01/2023		

Category C Insurance Loss. Vehicle Extensively Damaged But Repairable -Insurer Decided Not To Repair
Last service 09/01/2023 at 83,945 miles- 18 main dealer services

Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Radio/CD
- Front armrest
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Corroded
Light



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: A Post nsf
Scratched
UpTo 25mm Thru Paint



7: Aperture Seal nsr
Broken
Replace



8: Door nsf
Poor Previous Repair
Rippled UpTo 30%



9: Qtr Panel nsr
Rusted
Over 5mm



10: Wheel nsr
Corroded
Light



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Rusted
Over 5mm



13: Wheel osr
Corroded
Light



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osf
Poor Previous Repair
Rippled UpTo 30%



16: Wing osf
Poor Previous Repair
Poor Paint



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK