



VEHICLE INSPECTION REPORT

AJ10ZKW

Ford S-Max 2.0 EcoBoost Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/06/2010	Keys	2	CAP Clean	£1,375.00
Year	2010	Service history	Yes	CAP Average	£990.00
Mileage	114,091 Miles Warranted	Service documents	Service Book	CAP Below	£575.00
Fuel Type	PETROL	Number of stamps	10	Gearbox	AUTOMATIC
Colour	BLACK	Last service date	14/05/2024	Gears	6
VIN	WF0SXXGBWSAJ10391	Last service miles	101,283	Doors	5
Body Style	MPV	MOT Due	13/01/2027		

Last service 14/05/2024 at 101,283 miles- 10 services (5 main dealer)
Book and print Exhaust blowing

Tyres


NSF	SUNNY	3.0mm
NSR	KORMORAN	6.0mm
OSF	BUDGET	5.0mm
OSR	KORMORAN	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door Moulding osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osr
Chipped
1 To 5



5: Door osr
Chipped
Edge Chip




6: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



7: Tailgate
Chipped
1 To 5



8: Bumper Rear
Chipped
1 To 5



9: Roof
Rusted
Over 5mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: D Post ns
Rusted
Over 5mm



12: Wheel nsr
Scratched
Up To 50mm



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door nsf
Chipped
1 To 5



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Poor Previous Repair
Paint Flake



18: A Post os
Chipped
1 To 5



19: Sill ns
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK