



VEHICLE INSPECTION REPORT

EO64ULW

Vauxhall Mokka 1.7 CDTi Exclusiv 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	14/01/2015	Body Style	Hatchback	Last service miles	61,304
Year	2015	Keys	2	MOT Due	11/10/2026
Mileage	68,441 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	10	Doors	5
VIN	W0LJC7EL2FB094174	Last service date	15/07/2025		

£90 ADDITIONAL FEE

last service 15/7/25 @ 61,304 miles (10 services 7 main dealer) Service spanner display
Code 82 and 89 displays

Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door nsr
Chipped
Edge Chip



6: Other
N/A
N/A



7: Tailgate
Chipped
1 To 5




8: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



9: Wheel osr
Scratched
Over 50mm



10: Door osr
Poor Previous Repair
Poor Paint



11: Door osr
Dented
Between 10mm + 30mm



12: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Screen Front
Chipped
UpTo 10mm



14: Door osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK