



VEHICLE INSPECTION REPORT

GF59VEH

Volkswagen Passat 2.0 Highline TDI CR DPF 170 5dr

Accident Damage

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date 11/11/2009

Year 2009

Mileage 164,094 Miles
Warranted

Fuel Type DIESEL

Colour SILVER

VIN WVWZZZ3CZAE048309

Body Style Estate

Keys 1

Service history Yes

Service documents Printout

Number of stamps 4

Last service date 21/09/2012

Last service miles 42,776

CAP Clean £830.00

CAP Average £430.00

CAP Below £175.00

Gearbox MANUAL

Gears 6

Doors 5

£90 ADDITIONAL FEE

Last service 21/09/2012 at 42,776 miles- 4 main dealer services

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair

MOT failure Suspension noise from front

Roof lining sagged

Low clutch

Osf window does not work

Osf door does not open from outside

Eml light on car has been plugged in and detects intake manifold runner position sensor switch circuit low bank 1

Tyres

NSF SUNNY 5.0mm

NSR BUDGET 5.0mm

OSF BUDGET 5.0mm

OSR SUNNY 5.0mm

Spare

Features


- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos







Condition Check



Damage Photos



1: Wing osf
Dented
Over 30% Of Panel



2: Door osf
Dented
With Paint Damage



3: Door Moulding osf
Broken
Replace



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Wheel osf
Scratched
Over 50mm



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Wheel nsr
Scratched
Over 50mm




12: Door nsr
Chipped
1 To 5



13: Door Mirror Assy nsf
Broken
Replace



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Insecure
Action Required

16: Bonnet
Chipped
Multiple Chips



17: Bumper Front
Scratched
25 to 100mm Thru Paint

18: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
		Steering	OK