



VEHICLE INSPECTION REPORT

FA17AXX

Ford KA+ 1.2 85 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/07/2017	Keys	2	CAP Clean	£3,450.00
Year	2017	Service history	Yes	CAP Average	£2,925.00
Mileage	76,836 Miles Warranted	Service documents	Service Book	CAP Below	£2,400.00
Fuel Type	PETROL	Number of stamps	9	Gearbox	MANUAL
Colour	BLACK	Last service date	09/05/2026	Gears	5
VIN	MAJUXXMTKUH72739	Last service miles	74,808	Doors	5
Body Style	Hatchback	MOT Due	17/05/2027		

£90 ADDITIONAL FEE

Last service 09/05/2026 at 74,808 miles- 9 services
Book and print Engine runs fine with tapping noise

Tyres


NSF	BUDGET	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: A Post ns
Scratched
UpTo 25mm Thru Paint



5: Screen Front
Cracked
Replace



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Lamp nsr
Broken
Replace



12: Tailgate
Scratched
Over 25mm Thru Paint




13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Qtr Panel osr
Dented
With Paint Damage



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
1 To 5



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Roof
Scratched
Over 25mm Thru Paint



21: Carpets Front
Torn
Over 10mm

Interior

Carpets Condition	Poor	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK