



VEHICLE INSPECTION REPORT

HV14AEP

Seat Toledo 1.4 TSI SE 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2014	Keys	2	CAP Clean	£1,750.00
Year	2014	Service history	Yes	CAP Average	£1,350.00
Mileage	112,645 Miles Warranted	Service documents	Service Book	CAP Below	£950.00
Fuel Type	PETROL	Number of stamps	13	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	27/03/2026	Gears	7
VIN	VSSZZZNHZE1012674	Last service miles	108,328	Doors	5
Body Style	Hatchback	MOT Due	15/08/2026		

£100 ADDITIONAL FEE

Last service 27/03/2026 at 108,328 miles- 13 services (3 main dealer)

Book and print

Tyres

NSF	HANKOOK	5.0mm
NSR	ACCELERA	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Insurance telematics
- Remote central locking
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Centre Console Front
Scuffed
Over 25mm



3: Bonnet
Poor Previous Repair
Paint Flake



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Scratched
Over 25mm Thru Paint




8: Sill ns
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
UpTo 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Boot Lid
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint




14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Between 10mm + 30mm



18: Door osf
Scratched
Over 25mm Thru Paint




19: Wing osf
Dented
Between 10mm + 30mm



20: Wing osf
Scratched
UpTo 25mm Thru Paint



21: Wheel of
Scratched
Over 50mm



22: Roof
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK