



VEHICLE INSPECTION REPORT

GX63BKK

VAUXHALL ASTRA 1.6T 16V SRi [180] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/09/2013	Body Style	Hatchback	Last service miles	70,437
Year	2013	Keys	2	MOT Due	25/09/2026
Mileage	75,601 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	12	Doors	5
VIN	W0LPF6EJ1EG001589	Last service date	29/08/2025		

Last service 29/08/2025 at 70,437 miles- 12 services (3 main dealer) Add coolant message displayed
Service parking assist
Exhaust blowing

Tyres


NSF	NEXEN	4.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	Damaged
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Fascia Trim
Damaged
Replace



2: Tyre osf
Damaged
Replace



3: Bonnet
Dented
Between 10mm + 30mm



4: Bonnet
Scratched
Over 25mm Thru Paint



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Sill ns
Dented
With Paint Damage



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Tailgate
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osr
Dented
Between 10mm + 30mm



20: Door osf
Scratched
Over 25mm Thru Paint



21: Wing osf
Scratched
Over 25mm Thru Paint



22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK