



# VEHICLE INSPECTION REPORT

**MM17WPW**

## Vauxhall Astra 1.6 CDTi 16V SRi 5dr

Cat: S

Inspection

Serious Damage?

No

VAT

Margin

V5

Present

Details

Reg. date

18/07/2017

VIN

W0LBF6EK6HG181515

Gearbox

MANUAL

Year

2017

Body Style

Hatchback

Gears

6

Mileage

54,054 Miles  
Warranted

Keys

1

Doors

5

Fuel Type

DIESEL

Service history

None

Colour

RED

MOT Due

25/06/2027

nama

GRADE 5

Category S Insurance Loss. X2 2019 and 2020 Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair

NO SERVICE Spare rear lamp in boot

Service due message displayed

Intermittent engine rattle

Knocking front suspension

Rear windows faulty

|              |        |         |
|--------------|--------|---------|
| <b>Tyres</b> |        |         |
| <b>NSF</b>   | WINRUN | Damaged |
| <b>NSR</b>   | WINRUN | 5.0mm   |
| <b>OSF</b>   | ROVELO | 4.0mm   |
| <b>OSR</b>   | ROVELO | 5.0mm   |
| <b>Spare</b> |        |         |

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Lane departure warning
- Central locking
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

## Photos





## Condition Check




## Damage Photos



1: Tyre nsf  
Damaged  
Replace



2: Bumper Front  
Insecure  
Action Required




3: Bonnet  
Poor Previous Repair  
Paint Flake



4: Bumper Front  
Poor Previous Repair  
Poor Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Poor Previous Repair  
Poor Paint



7: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



8: Door nsf  
Poor Previous Repair  
Rippled UpTo 30%



9: Door nsr  
Poor Previous Repair  
Rippled UpTo 30%



10: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



11: Wheel nsr  
Scratched  
Over 50mm



12: Bumper Rear  
Dented  
With Paint Damage



13: Lamp nsr  
Broken  
Replace



14: Tailgate  
Poor Previous Repair  
Paint Flake



15: Roof  
Dented  
Over 30mm



16: Qtr Panel osr  
Dented  
Over 30mm



17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Dented  
Over 30mm



19: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



20: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



21: Wheel osf  
Scratched  
Over 50mm



22: Wing osf  
Dented  
Over 30mm

Interior

|                  |         |                      |         |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition   | Average | Odour                | No      |

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                          |       |                                                |       |
|--------------------------|-------|------------------------------------------------|-------|
| Engine Runs              | OK    | Gearbox 1st and Reverse Test                   | OK    |
| Brakes                   | OK    | Clutch Slip Test from Static                   | OK    |
| Parking Brake            | OK    | Gearbox Static Gear Selection (engine running) | OK    |
|                          |       | No Excessive Smoking                           | OK    |
| EML light illuminated    | OK    | Oil warning light illuminated                  | OK    |
| Airbag light illuminated | OK    | Service indicator light illuminated            | Fault |
| ABS light illuminated    | OK    |                                                |       |
| Windows                  | Fault | Radio                                          | OK    |
|                          |       | Steering                                       | OK    |