



VEHICLE INSPECTION REPORT

GY67JVO

Toyota C-Hr 1.2T Dynamic 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/11/2017	Body Style	Hatchback	Last service miles	62,995
Year	2017	Keys	2	MOT Due	30/09/2026
Mileage	68,753 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	PETROL	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	7	Doors	5
VIN	NMTKY3BX80R025527	Last service date	01/09/2026		

Last Service - 01.09.2025 at 62995 miles (7 main dealer services)

Tyres



NSF	BUDGET	5.0mm
NSR	MICHELIN	4.0mm
OSF	KUMHO	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bumper Front
Poor Previous Repair
Poor Paint



2: Bonnet
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Poor Previous Repair
Rippled Up To 30%



5: Door nsr
Chipped
1 To 5



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel osr
Chipped
1 To 5




8: Wheel osr
Scratched
Over 50mm



9: Door osr
Dented
Between 10mm + 30mm



10: Door osr
Scratched
UpTo 25mm Thru Paint



11: Door osf
Chipped
1 To 5



12: Wing osf
Chipped
1 To 5



13: Wheel osf
Scratched
Over 50mm



14: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK