



VEHICLE INSPECTION REPORT

RE56OFR

Honda Jazz 1.4 i-DSi Sport 5dr CVT-7

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2006	Keys	1	CAP Clean	£890.00
Year	2006	Service history	Yes	CAP Average	£480.00
Mileage	93,131 Miles Warranted	Service documents	Printout	CAP Below	£225.00
Fuel Type	PETROL	Number of stamps	2	Gearbox	CVT
Colour	BLUE	Last service date	07/11/2023	Gears	1
VIN	JHMGD18906S234831	Last service miles	74,284	Doors	5
Body Style	Hatchback	MOT Due	07/04/2027		

Last service 07/11/2023 at 74,284 miles- 2 services

Tyres

NSF	BUDGET	5.0mm
NSR	PIRELLI	4.0mm
OSF	PACE	5.0mm
OSR	SAILUN	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



12: Bumper Rear
Dented
With Paint Damage



13: Roof
Dented
2 Or Less UpTo 10mm



14: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



15: Wheel osr
Scratched
Over 50mm



16: Sill os
Rusted
Over 5mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK