



VEHICLE INSPECTION REPORT

YS70YGD

Ford Transit Custom 2.0 EcoBlue 130ps Low Roof Limited Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

nama
GRADE
4

Details

Reg. date 09/12/2020

Year 2020

Mileage 131,058 Miles
Warranted

Fuel Type DIESEL

Colour WHITE

VIN WF0YXXTTGYLY76174

Body Style Panel Van

Keys 2

Service history Yes

Service documents Printout

Number of stamps 4

Last service date 13/11/2025

Last service miles 126,900

MOT Due 11/11/2026

Gearbox MANUAL

Gears 6

£100 ADDITIONAL FEE

NEW CLUTCH & FLYWHEEL 04/03/2025 @120,072 MILES

TIMING BELT REPLACED 08/07/2025 @ 124,760 MILES

LAST SERVICE 13/11/2025 @ 126,900 MILES (4 SERVICES)

Tyres

NSF HANKOOK 4.0mm

NSR HANKOOK 5.0mm

OSF HANKOOK 4.0mm

OSR HANKOOK 5.0mm



Spare

Features


- Bluetooth connection
- Rear parking sensor
- Drivers airbag
- Cruise control
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Heated front seat
- Front electric windows
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Seat Base Cover osf
Burn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
Over 30mm



9: Qtr Panel nsr
Rusted
Over 5mm



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Dented
With Paint Damage



13: Roof
Dented
Over 30mm



14: Qtr Panel osr
Dented
Over 30mm



15: Wheel osr
Scratched
Over 50mm



16: Door osf
Chipped
Edge Chip




17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm



19: A Post os
Chipped
1 To 5



20: Roof
Chipped
Edge Chip



21: Handle Outer nsr
Scratched (Painted)
Over 25mm Thru Paint

22: Tyre nsr
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK